

Imray Correction Notice

IC2300.8

07 September 2012

Chart 2300+8 WGS 84

Edition Jul 2008

Date of printing Jul 2008

The following corrections should be noted:

1 Tor Bay

Insert Y spher Lt buoy Fl(5)Y.20s in 50°26'00N 3°31'10W (ILNW 376/08)

2 Teignmouth (Plan A)

Insert Lt buoys:

G con Fl.G.2s in 50°32'44N 3°29'25W

R can Fl.R.2s in 50°32'35N 3°29'36W

Move G con Lt buoy Fl.G.2s in 50°32'38N 3°29'77W to 50°32'38N 3°29'70W. (ILNW 446/08)

3 Approaches to Teignmouth

Delete *Obstn* depth 0.3m in 50°32'65N 3°29'28W (ILNW 1/09)

4 Brixham Harbour (Plan D)

Delete Lt Q at Eastern Pier in 50°23'92N 3°30'65W (ILNW 46/09)

5 Tor Bay, Berry Head

Amend range of **Berry Head** Lt to 19M in 50°24'0N 3°29'0W (ILNW 128/09)

6 Brixham

Work on the new quay in the vicinity of the existing Fish Quay has now been completed.

Insert Lt Q.G in 50°23'95N 3°30'77W and delete *Igd Works in progress (2008)* close by. (ILNW 349/09)

7 Tor Bay

Insert:

Y spher Lt buoy Fl.Y.5s in 50°24'44N 3°31'68W

Marine farm sym in 50°24'40N 3°31'70W

Delete former marine farm limit and Y spher Lt buoy Fl.Y close by. (ILNW 233/12)

8 Brixham Harbour (Main chart & Plan D)

Delete Lt Dirlso.WRG.5s4m6M, and assoc. sectors, in 50°23'83N 3°30'56W (ILNW 309/12)

9 Notification of New Edition

A new September 2012 edition of this sheet will shortly be published. In addition to the listed corrections, revised depths are displayed (in particular at Teignmouth) as well as the harbour developments at Torquay and Brixham. (ILNW 362/12)